Oil Field Environmental Incident Summary

Responsible Party: CONDOR PETROLEUM, INC. **Well Operator:** CONDOR PETROLEUM, INC.

Well Name: NELS WOLD 1 **Field Name:** NORTH TIOGA

RTH TIOGA Well File #: 13023

Date Incident:7/17/2014Time Incident:11:25Facility ID Number:County:BURKETwp:159Rng:94Sec:6Qtr:

Location Description: Thorson/Nels Wold Tank Battery

Submitted By: Emily Drabbs Received By:

Contact Person: Steve Tracey

PO BOX 339

TIOGA, ND 58852

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:5 MileDistance Nearest Water Well:1 Mile

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 150 Barrels

Other 150 barrels

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/6/2015 Clean Up Concluded: 7/20/2014

Risk Evaluation:

n/a

Areal Extent:

Potential Environmental Impacts:

n/a

Action Taken or Planned:

reset switch, will such water out of dike and take to the nearest salt water disposal

Wastes Disposal Location: Nearest salt water disposal, about 1 mile away.

Agencies Involved:

Updates

Date: 7/17/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on location within the diking according to the report. NDIC retains oversight.